




Have a look at the layers to plan out the etching and cutting. Raster the front side of the coins and cut the alignment holes. Flip the board over and use the alignment holes to... well... align the back. Turn off the front layers, turn on the back ones. Raster the back sides. Then turn on the cut layer and cut the coins out.





Have a look at the layers to plan out the etching and cutting. Raster the front side of the coins and cut the alignment holes. Flip the board over and use the alignment holes to... well... align the back. Turn off the front layers, turn on the back ones. Raster the back sides. Then turn on the cut layer and cut the coins out.



Have a look at the layers to plan out the etching and cutting. Raster the front side of the coins and cut the alignment holes. Flip the board over and use the alignment holes to... well... align the back. Turn off the front layers, turn on the back ones. Raster the back sides. Then turn on the cut layer and cut the coins out.